

WELL LOG AND DRILLING REPORT

ORIGINAL

State of Ohio

PLEASE USE PENCIL
OR TYPEWRITER.
DO NOT USE INK.

DEPARTMENT OF NATURAL RESOURCES

Division of Water
1562 W. First Avenue
Columbus, Ohio

No. 247547

County Summit Township Bath Section of Township SouthwestOwner C. C. D^e Mott Address 1290 Revere rd.Location of property 1 1/2 mi. N.W. of Smith rd. on Revere rd.

CONSTRUCTION DETAILS

Casing diameter 5 Length of casing 73 ft Pumping rate 3 G.P.M. Duration of test 4 hrs.
 Type of screen none Length of screen ✓ Drawdown 40 ft. Date 2-11-63
 Type of pump jet Developed capacity 3 gal. per min.
 Capacity of pump Static level—depth to water 48 ft.
 Depth of pump setting Pump installed by _____
 Date of completion 2-11-63

BAILING OR PUMPING TEST

WELL LOG

Formations
Sandstone, shale, limestone,
gravel and clay

From

To

0 Feet

4 Ft.

4 "

8 "

31 "

37 "

37 "

54 "


64 "

55 "

Sandy Clay
 Sand & Gravel
 Sandy Blue Clay
 Sand & Gravel
 Gray Shale

water at 74 ft.

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.

See reverse side for instructions

Drilling Firm H. S. HamiltonDate 2-11-63Address 2187 Graham rd
Ham, OhioSigned H. S. Hamilton