

WELL LOG AND DRILLING REPORT

PLEASE USE PENCIL
OR TYPEWRITER.
DO NOT USE INK.

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1562 W. First Avenue
Columbus, Ohio

No. 249294

County Belmont Township Warren Section of Township 19
Owner Glenn Hanes Address Barnesville, O RR 1
Location of property 1 1/2 mi south of Barnesville on Rt 8

CONSTRUCTION DETAILS

Casing diameter 6 3/8 in Length of casing 20 ft
Type of screen — Length of screen —
Type of pump —
Capacity of pump —
Depth of pump setting —
Date of completion Oct 31, 1962

BAILING OR PUMPING TEST


Pumping rate 10 G.P.M. Duration of test 5 hrs.
Drawdown — ft. Date Oct 31, 1962
Developed capacity —
Static level—depth to water 21 ft.
Pump installed by owner

WELL LOG

Formations Sandstone, shale, limestone, gravel and clay	From	To
<u>yellow shale</u>	<u>0 Feet</u>	<u>20 Ft.</u>
<u>limestone</u>	<u>20</u>	<u>57</u>
<u>water at 21 ft</u>		

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



See reverse side for instructions

Drilling Firm Glenn E. Warrick Date Oct 31, 1962
Address 507 N. Lincoln Ave Signed Glenn E Warrick
Barnesville, Ohio

SR 800

44