

WELL LOG AND DRILLING REPORT

ORIGINAL

PLEASE USE PENCIL
OR TYPEWRITER.
DO NOT USE INK.

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1562 W. First Avenue
Columbus, Ohio

No. 258886

County Clermont Township Pierce Section of Township _____

Owner Leslie Craig Address _____

Location of property nine mile Rd north of Narddyke Rd.

CONSTRUCTION DETAILS

Casing diameter 5 1/4" Length of casing 21'
Type of screen _____ Length of screen _____
Type of pump _____
Capacity of pump _____
Depth of pump setting _____
Date of completion Aug 17th 63

BAILING OR PUMPING TEST


Pumping rate 1 G.P.M. Duration of test 2 hrs.
Drawdown 0 ft. Date Aug 17th 63
Developed capacity 1 G.P.M.
Static level—depth to water 15 ft.
Pump installed by Furner

WELL LOG

Formations Sandstone, shale, limestone, gravel and clay	From	To
<u>Clay + Gravel</u>	<u>0 Feet</u>	<u>20 Ft.</u>
<u>Limestone</u>	<u>20</u>	<u>80</u>
<u>Water at 33'</u>		

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



See reverse side for instructions