

WELL LOG AND DRILLING REPORT

ORIGINAL

PLEASE USE PENCIL
OR TYPEWRITER.
DO NOT USE INK.

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1562 W. First Avenue
Columbus, Ohio

No. 262040

County Ashland Township Millin Section of Township _____
Owner Floyd Pryor Address 899 Forest Drive Lincoln Hts. Mass
Location of property 1 1/2 mi S. of R 30 on 603 then 5/10 mi West

CONSTRUCTION DETAILS

Casing diameter 4 1/4 Length of casing 87' 8"
Type of screen _____ Length of screen _____
Type of pump _____
Capacity of pump _____
Depth of pump setting _____
Date of completion _____

BAILING OR PUMPING TEST


Pumping rate _____ G.P.M. Duration of test _____ hrs.
Drawdown 0 ft. Date _____
Developed capacity _____
Static level—depth to water 29 ft.
Pump installed by _____

WELL LOG

Formations Sandstone, shale, limestone, gravel and clay	From	To
	0 Feet	Ft.
Clay	0	4
Gravel	4	17
Clay Gravel	17	60
Sand	60	72
Clay Gravel	72	85
Shale Gray	85	89
Drawdown		70
Static Level		29
Depth		89

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



See reverse side for instructions

Drilling Firm Clyde Kendall
Address Ashland

Date 3-12-62
Signed Clyde Kendall

SR 603

58