

WELL LOG AND DRILLING REPORT

ORIGINAL

PLEASE USE PENCIL
OR TYPEWRITER.
DO NOT USE INK.

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1562 W. First Avenue
Columbus, Ohio

No. 262042

County Richland Township Mourne Section of Township 1
Owner Frank Strausky Address P.O. 1, Lucas, Ohio
Location of property 1/4 East of Lucas on Rt 39 to State Rd then
1/8 mi so on State Rd

CONSTRUCTION DETAILS

BAILING OR PUMPING TEST

Casing diameter 4 3/4 Length of casing 20' Pumping rate.....G.P.M. Duration of test.....hrs.
Type of screen..... Length of screen..... Drawdown.....ft. Date.....
Type of pump..... Developed capacity.....
Capacity of pump..... Static level—depth to water 91' ft.
Depth of pump setting..... Pump installed by.....
Date of completion.....


WELL LOG

SKETCH SHOWING LOCATION

Formations Sandstone, shale, limestone, gravel and clay	From	To
	0 Feet	Ft.
Clay	0	12'
Clay Gravel	12'	16'
Shale Brown	16'	52'
Shale Gray	52'	72'
Sand Rock	72	104'
Shale Gray	104	143'
Water at	50-94-137'	
Standing Water		35'
Static Level		91
Depth		143

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.

N.



S.

See reverse side for instructions

Drilling Firm Clyde Kendall Date 4-4-62
Address Ashland Ohio Signed Clyde Kendall

LOCATED

(31)