

WELL LOG AND DRILLING REPORT

ORIGINAL

State of Ohio
 DEPARTMENT OF NATURAL RESOURCES
 Division of Water
 1562 W. First Avenue
 Columbus, Ohio

No. 262046

County Richland Township Madison Section of Township 23
 Owner William Hale Address 662 Sunset Drive, Mansfield
 Location of property _____

CONSTRUCTION DETAILS	BAILING OR PUMPING TEST
Casing diameter <u>4 1/4</u> Length of casing <u>75'</u>	Pumping rate _____ G.P.M. Duration of test _____ hrs.
Type of screen _____ Length of screen _____	Drawdown <u>0</u> ft. Date _____
Type of pump _____	Developed capacity _____
Capacity of pump _____	Static level—depth to water <u>99'</u> ft.
Depth of pump setting _____	Pump installed by _____
Date of completion _____	

WELL LOG	Formations	From	To	SKETCH SHOWING LOCATION
	Sandstone, shale, limestone, gravel and clay	0 Feet	Ft.	
	Clay	0	11'	N. E.
	Clay Gravel	11'	75'	
	Shale Gray	75	80	
	Sand Rock	80	141	
	Depth		141	
	Static Level		99	

Drilling Firm Clyde Kendall Date 5-24-62
 Address Ashland CO Signer Clyde Kendall