

WELL LOG AND DRILLING REPORT

ORIGINAL

State of Ohio

PLEASE USE PENCIL
OR TYPEWRITER.
DO NOT USE INK.

DEPARTMENT OF NATURAL RESOURCES

Division of Water
1562 W. First Avenue
Columbus, Ohio

No. 265546

County Summit Township Norton Section of Township _____
 Owner A. E. Helsel Address 192 Second St. S.W.
 Location of property 4176 Hawaii Ave Barberton, Ohio

CONSTRUCTION DETAILS

BAILING OR PUMPING TEST

Casing diameter 4" Length of casing 31'5"Pumping rate 12 G.P.M. Duration of test 1 hrs.Type of screen — Length of screen —Drawdown 60' ft. Date 7-1-62

Type of pump _____

Developed capacity 126 P.M.

Capacity of pump _____

Static level—depth to water 15' ft.

Depth of pump setting _____

Pump installed by _____

Date of completion _____

WELL LOG

SKETCH SHOWING LOCATION

Formations
Sandstone, shale, limestone,
gravel and clay

From

To

0 Feet

12 Ft.

Clay
Soft shale
Hard shale
Sandstone
Total Depth

10'20'20'37'37'68'68'Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.

N.

W. Hawaii

E.

Hametown Rd.

S.

See reverse side for instructions

Drilling Firm A. C. SpencerDate 7-1-62Address Box 131 Clinton, OhioSigned A. C. Spencer