

WELL LOG AND DRILLING REPORT

ORIGINAL

PLEASE USE PENCIL
OR TYPEWRITER.
DO NOT USE INK.

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1562 W. First Avenue
Columbus, Ohio

No. 268928
OK

County MORROW Township Congress Section of Township 33
Owner Clark Higgins Address R-1 Mt. Gilcard, O.
Location of property 4 mi. E. Mt. Gilcard on Co. Rd 93 + Twp Rd 108

CONSTRUCTION DETAILS

Casing diameter 4" Length of casing 80'
Type of screen _____ Length of screen _____
Type of pump _____
Capacity of pump _____
Depth of pump setting _____
Date of completion 29 Jan '62

BAILING OR ~~PUMPING~~ TEST


Pumping rate 12 G.P.M. Duration of test 4 hrs.
Drawdown 13 ft. Date _____
Developed capacity _____
Static level—depth to water 40 ft.
Pump installed by _____

WELL LOG

Formations Sandstone, shale, limestone, gravel and clay	From	To
Top Soil	0 Feet	<u>2</u> Ft.
Clay - Sand & Gravel	<u>2</u>	<u>8</u>
Sand & Gravel	<u>8</u>	<u>26</u>
Clay	<u>26</u>	<u>74</u>
Sand	<u>74</u>	<u>78</u>
Gravel	<u>78</u>	<u>80</u>

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



S.

See reverse side for instructions

Drilling Firm Randolph & Fisher
Address R-3 Mt. Gilcard, O.

Date 29 Jan, 62
Signed R. B. Fisher

130