

WELL LOG AND DRILLING REPORT

ORIGINAL

PLEASE USE PENCIL
OR TYPEWRITER.
DO NOT USE INK.

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1562 W. First Avenue
Columbus, Ohio

No. 271707

County Lorain Township Columbia Section of Township N.W.
Owner Charles V. Prindle Address Columbia Station, O.
Location of property 12464 Root Rd. 3/4 mi W. of Station Rd. W. side

CONSTRUCTION DETAILS

Casing diameter 5 1/2 Length of casing 44
Type of screen Length of screen
Type of pump
Capacity of pump
Depth of pump setting
Date of completion

BAILING OR PUMPING TEST


Pumping rate G.P.M. Duration of test hrs.
Drawdown ft. Date
Developed capacity
Static level—depth to water ft.
Pump installed by

WELL LOG

Formations Sandstone, shale, limestone, gravel and clay	From	To
	0 Feet	Ft.
<u>yellow clay</u>		<u>10</u>
<u>gray sand & gravel</u>	<u>10</u>	<u>44</u>
<u>gray shale</u>	<u>44</u>	<u>51</u>
<u>Belea</u>	<u>51</u>	<u>76</u>
<u>water came in</u>	<u>60 to 70</u>	
<u>good supply</u>		

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads



See reverse side for instructions

Drilling Firm Luke Fitzsimmons & Co.
Address Valley City, O.

Date Feb 2, 1963
Signed Mrs. L. Fitzsimmons

⑨