

WELL LOG AND DRILLING REPORT

ORIGINAL

97 ✓

PLEASE USE PENCIL
OR TYPEWRITER.
DO NOT USE INK.

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1562 W. First Avenue
Columbus, Ohio

No. 271738

County Clark Township Bethel Section of Township 10
Owner Harner Sitter Address N. Carlisle #3
Location of property 1/4 mi N. of Sunnysville off 440

CONSTRUCTION DETAILS

Casing diameter 5 7/8 Length of casing 116
Type of screen _____ Length of screen _____
Type of pump _____
Capacity of pump _____
Depth of pump setting _____
Date of completion _____

BAILING OR PUMPING TEST

Pumping rate _____ G.P.M. Duration of test _____ hrs.
Drawdown 15 ft. Date _____
Developed capacity 1100
Static level—depth to water 63 ft.
Pump installed by _____

WELL LOG


Formations Sandstone, shale, limestone, gravel and clay	From	To
<u>Clay</u>	0 Feet	<u>16</u> Ft.
<u>Sand</u>	<u>16</u>	<u>21</u>
<u>Clay</u>	<u>21</u>	<u>102</u>
<u>Sand</u>	<u>102</u>	<u>115</u>
<u>Gravel</u>	<u>115</u>	<u>116</u>
<u>water at 116</u>		

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.

N.

Section 10

W.  E.

S.

See reverse side for instructions

Drilling Firm P. P. Limer
Address Bethel

Date 11/10/13
Signed P. P. Limer

L