

WELL LOG AND DRILLING REPORT

ORIGINAL

PLEASE USE PENCIL
OR TYPEWRITER.
DO NOT USE INK.

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1562 W. First Avenue
Columbus, Ohio

No. 273789

County Montgomery Township Madison Section of Township 21

Owner Arthur Myers Address 4661 Hickcreek Pike

Location of property 1/4 mile N. West of Little Richmond Rd. Hickcreek Pike

CONSTRUCTION DETAILS

Casing diameter 6 Length of casing 44'

Type of screen Length of screen

Type of pump Submersible

Capacity of pump

Depth of pump setting

Date of completion

BAILING OR PUMPING TEST

Pumping rate 2 gal G.P.M. Duration of test 2 1/2 hrs.

Drawdown 50 ft. Date Nov 1 - 68

Developed capacity 160 gal per Hr

Static level—depth to water 35 feet ft.


Pump installed by Mike Shank

WELL LOG

Formations Sandstone, shale, limestone, gravel and clay	From	To
clay gravel	0 Feet	5 Ft.
" "	5	10
" gravel	10	15
" "	15	20
" sand	20	30
" "	30	43
lime stone	43	67

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



Drilling Firm Mike Shank

Address 2382 N Union Rd

Date Nov 1 - 68

Signed Mike Shank

1649

150