

WELL LOG AND DRILLING REPORT

ORIGINAL

PLEASE USE PENCIL
OR TYPEWRITER
DO NOT USE INK.

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1562 W. First Avenue
Columbus 12, Ohio

No 275319

County STARK Township BETHELEM Section of Township 1
Owner KENNETH WOLF Address 6530-BETH AVE S.W.
Location of property 6530-Bethane S.W. RD #1, Navarre

CONSTRUCTION DETAILS

Casing diameter 4 in Length of casing 27 FT
Type of screen NONE Length of screen —
Type of pump DEEP WELL
Capacity of pump 8 GPM
Depth of pump setting 35 FT
Date of completion JUNE 23-1966

BAILING OR PUMPING TEST

Pumping Rate 15 G.P.M. Duration of test 2 hrs.
Drawdown 1 ft. Date JUNE
Static level-depth to water 18 ft.
Quality (clear, cloudy, taste, odor) —
Pump installed by HANK MARGO


WELL LOG

Formations Sandstone, shale, limestone, gravel and clay	From	To
	0 Feet	Ft.
CLAY	0	20
GRAY SANDY SHALE	7	27
GRAY LIME ROCK	3	30
GRAY SANDY SHALE	22	52

Water from
30 ft to 52 ft

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



See reverse side for instructions

Drilling Firm Carl Davis
Address RD #1, Navarre

Date June 23-1966
Signed Carl Davis