

WELL LOG AND DRILLING REPORT

ORIGINAL

PLEASE USE PENCIL
OR TYPEWRITER
DO NOT USE INK.

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1562 W. First Avenue
Columbus 12, Ohio

No 275320

County STARK Township BETHELEM Section of Township 1
Owner PIUS SOEHNLEN Address R.D. 1, NAVAARRE
Location of property 4143 BETH S.W.

CONSTRUCTION DETAILS	BAILING OR PUMPING TEST
Casing diameter <u>4 in</u> Length of casing <u>44 ft</u>	Pumping Rate <u>8</u> G.P.M. Duration of test <u>2</u> hrs.
Type of screen <u>NONE</u> Length of screen <u>✓</u>	Drawdown <u>4</u> ft. Date <u> </u>
Type of pump <u>SHALLOW WELL</u>	Static level-depth to water <u>17 1/2 ft</u> ft.
Capacity of pump <u>5 GPM</u>	Quality (<u>clear</u> , cloudy, taste, odor) <u> </u>
Depth of pump setting <u>25 FT</u>	
Date of completion <u>JULY 1-66</u>	Pump installed by <u>OWNER</u>

WELL LOG			SKETCH SHOWING LOCATION
Formations Sandstone, shale, limestone, gravel and clay	From 0 Feet	To Ft.	Locate in reference to numbered State Highways, St. Intersections, County roads, etc.
CLAY. SAND. BOLDERS CLAY	20	20	
	10	30	
GRAY. SOFT. SHALE	15	45	
DARK. GRAY. LIMESTONE	4	49	
GRAY SANDY SHALE STS OF LIME	22	71	

S.
See reverse side for instructions

Drilling Firm Carl Davis
Address R.D. 1, Navaarre

Date July 1-1966
Signed Carl Davis