

WELL LOG AND DRILLING REPORT

ORIGINAL

PLEASE USE PENCIL
OR TYPEWRITER
DO NOT USE INK.

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1562 W. First Avenue
Columbus 12, Ohio

No 276257

County Putnam Township Perry Section of Township 23 26
Owner Harold Barnhart Address R-2 Cloverdale, O.
Location of property Road 20J 1/4 mile north State Rt-114

CONSTRUCTION DETAILS			BAILING OR PUMPING TEST	
Casing diameter <u>4 1/4"</u>	Length of casing <u>46'</u>		Pumping Rate <u>8</u> G.P.M.	Duration of test <u> </u> hrs.
Type of screen <u>None</u>	Length of screen <u> </u>		Drawdown <u> </u> ft.	Date <u> </u>
Type of pump <u> </u>			Static level-depth to water <u>30'</u>	ft.
Capacity of pump <u> </u>			Quality (clear, cloudy, taste, odor) <u>cloudy</u>	
Depth of pump setting <u> </u>				
Date of completion <u>Aug 20 - 1966</u>			Pump installed by <u> </u>	
WELL LOG			SKETCH SHOWING LOCATION	
Formations Sandstone, shale, limestone, gravel and clay	From	To	Locate in reference to numbered State Highways, St. Intersections, County roads, etc.	
<u>top Soil</u>	<u>0 Feet</u>	<u>3 Ft.</u>	N. State Rt 694 W. E. State Rt 114 S.	
<u>clay</u>	<u>3</u>	<u>27</u>		
<u>gravel</u>	<u>27</u>	<u>32</u>		
<u>clay</u>	<u>32</u>	<u>40</u>		
<u>shale</u>	<u>40</u>	<u>45</u>		
<u>Limestone</u>	<u>45</u>	<u>65</u>		
<u>water at 60'</u>			See reverse side for instructions	

Drilling Firm Steele-Fletcher-Barnhart Date Sept 9 - 1966
Address R-3 Col. Grove, O Signed Robert W. Steele