

WELL LOG AND DRILLING REPORT

ORIGINAL

PLEASE USE PENCIL
OR TYPEWRITER
DO NOT USE INK.

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1562 W. First Avenue
Columbus 12, Ohio

No. 276691

4171 SK 668

County Perry Township Reading Section of Township 28

Owner Frank Noll Address Somerset 4171 SR 668
R.R. 2

Location of property 3 1/2 M S. of Somerset on S.R. 668
3 1/2 M S. of Somerset on S.R. 668

CONSTRUCTION DETAILS

Casing diameter 8" Length of casing 24

Type of screen None Length of screen

Type of pump 10" mill

Capacity of pump Casing cemented

Depth of pump setting in well

Date of completion

BAILING OR PUMPING TEST

Pumping Rate 4 G.P.M. Duration of test 1/2 hrs.

Drawdown 110 ft. Date Dec. 15-65

Static level-depth to water 34 ft.

Quality (clear, cloudy, taste, odor)


Pump installed by

WELL LOG

Formations Sandstone, shale, limestone, gravel and clay	From	To
Soil	0 Feet	2 Ft.
Yellow clay	2	18
Yellow sandstone	18	42
Gray shale	42	100
Blue shale	100	110
Water @ 42		

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



See reverse side for instructions

LOCATED
322

Drilling Firm W.O. Melick 1496

Date 12-15-65

Address Somerset

Signed W.O. Melick

364