

(L)

WELL LOG AND DRILLING REPORT

ORIGINAL

PLEASE USE PENCIL
OR TYPEWRITER
DO NOT USE INK.

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1562 W. First Avenue
Columbus 12, Ohio

No 276807

County Medina Township Wadsworth Section of Township

Owner Frank J. Akman Address R.D. Wadsworth

Location of property Lt 45- Clearview Area Wadsworth Twp.

CONSTRUCTION DETAILS

Casing diameter 5" Length of casing 47'7"
Type of screen Length of screen
Type of pump
Capacity of pump
Depth of pump setting
Date of completion

BAILING OR PUMPING TEST


Bailed
Pumping Rate 20 G.P.M. Duration of test hrs.
Drawdown 10 ft. Date
Static level-depth to water 50 ft.
Quality (clear, cloudy, taste, odor)
Pump installed by Contractor

WELL LOG

Formations Sandstone, shale, limestone, gravel and clay	From	To
	0 Feet	6 Ft.
<u>well pit</u>		
<u>Brown clay & gravel</u>	6	20
<u>Shell rock</u>	20	26
<u>Clay & gravel</u>	26	38
<u>Blue Shelly Shale</u>	38	55
<u>Pebble rock</u>	55	60
<u>Grey sandstone</u>	60	72
<u>Brown Sandstone</u>	72	107
<u>Water</u>	72-85	
	90-95	

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



S.
See reverse side for instructions

Drilling Firm R.H. Harley

Address Burlington Ohio

Date Oct 1961

Signed