

WELL LOG AND DRILLING REPORT

ORIGINAL

PLEASE USE PENCIL
OR TYPEWRITER
DO NOT USE INK.

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1562 W. First Avenue
Columbus 12, Ohio

No 279871

County Allen Township Beth Section of Township 11
Owner Jack Centers Address Blue Lick Rd Lima
Location of property 3 mi north of Lima on Blue Lick Rd

CONSTRUCTION DETAILS		BAILING OR PUMPING TEST	
Casing diameter <u>4 1/4</u>	Length of casing <u>43</u>	Pumping Rate <u>10</u> G.P.M.	Duration of test <u>1</u> hrs.
Type of screen	Length of screen	Drawdown <u>none</u> ft.	Date <u>Jan 18 - 64</u>
Type of pump		Static level-depth to water <u>21</u> ft.	
Capacity of pump		Quality (clear, cloudy, taste, odor) <u>clear</u>	
Depth of pump setting			
Date of completion <u>Jan 18 1964</u>		Pump installed by	

WELL LOG			SKETCH SHOWING LOCATION	
Formations Sandstone, shale, limestone, gravel and clay	From	To	Locate in reference to numbered State Highways, St. Intersections, County roads, etc.	
<u>clay</u>	0 Feet	<u>40</u> Ft.		
<u>sand</u>	40	43		
<u>Lime Stone</u>	43	45		
<u>Water out</u>	45'			

Drilling Firm Waldron
Address 3100 Sheraton Rd

Date Jan 18 1964
Signed Gordon E. Waldron

