

# WELL LOG AND DRILLING REPORT

ORIGINAL

PLEASE USE PENCIL  
OR TYPEWRITER  
DO NOT USE INK.

State of Ohio  
DEPARTMENT OF NATURAL RESOURCES

Division of Water  
1562 W. First Avenue  
Columbus 12, Ohio

No 280832

County Lucas Township Deerbrook Section of Township

Owner Frank H. Long & Son Address

Location of property Lot 113 Krollman acres Crabtree<sup>2209</sup> Marshall

## CONSTRUCTION DETAILS

Casing diameter 5 5/8 Length of casing 34'  
Type of screen Length of screen  
Type of pump Deep well jet  
Capacity of pump 5 GPM  
Depth of pump setting 40  
Date of completion Nov 6, 1962

## BAILING OR PUMPING TEST


Bailing Pumping Rate 7 G.P.M. Duration of test 2 hrs.  
Drawdown 28 ft. Date Nov 5, 1961  
Static level-depth to water 12 ft.  
Quality (clear, cloudy, taste, odor) Clear  
Pump installed by M. Rose

## WELL LOG

| Formations<br>Sandstone, shale, limestone,<br>gravel and clay | From      | To           |
|---------------------------------------------------------------|-----------|--------------|
| <u>2 in</u>                                                   | 0 Feet    | <u>6</u> Ft. |
| <u>Clay + gravel</u>                                          | <u>6</u>  | <u>32</u>    |
| <u>Clay</u>                                                   | <u>32</u> | <u>34</u>    |
| <u>Shale grey</u>                                             | <u>34</u> | <u>45</u>    |
| <u>Water at 40'</u>                                           |           |              |

## SKETCH SHOWING LOCATION

Locate in reference to numbered  
State Highways, St. Intersections, County roads, etc.



Drilling Firm Morris Rose  
Address 68 N Longview St  
Dayton 32, 0

Date Nov. 19, 1962  
Signed M. Rose