

WELL LOG AND DRILLING REPORT

ORIGINAL

PLEASE USE PENCIL
OR TYPEWRITER
DO NOT USE INK.

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1562 W. First Avenue
Columbus 12, Ohio

N^o 281164

County Summit Township Bath Section of Township _____

Owner L. P. Tewksbury Address 3813 Ira Road, Bath, Ohio

Location of property 3813 Ira Road, Bath, Ohio

CONSTRUCTION DETAILS	BAILING OR PUMPING TEST
Casing diameter <u>5"</u> Length of casing <u>24'</u>	Bailing _____ Pumping Rate <u>10</u> G.P.M. Duration of test <u>1</u> hrs.
Type of screen <u>None</u> Length of screen _____	Drawdown <u>6</u> ft. Date <u>11/6/63</u>
Type of pump <u>None</u>	Static level-depth to water <u>22</u> ft.
Capacity of pump _____	Quality (clear, cloudy, taste, odor) <u>Clear</u>
Depth of pump setting _____	Pump installed by _____
Date of completion <u>11/6/63</u>	

WELL LOG			SKETCH SHOWING LOCATION
Formations Sandstone, shale, limestone, gravel and clay	From	To	Locate in reference to numbered State Highways, St. Intersections, County roads, etc.
Yellow Clay	0 Feet	16 Ft.	N. W. E. S.
Sandstone	16	23	
Shale Rock	23	60 T.	
			See reverse side for instructions

Drilling Firm L. P. Cranz Date 11/18/63

Address 2254 Ira Road, Akron 13, Ohio Signed L. P. Cranz