

WELL LOG AND DRILLING REPORT

ORIGINAL

State of Ohio

PLEASE USE PENCIL
OR TYPEWRITER
DO NOT USE INK.

DEPARTMENT OF NATURAL RESOURCES
Division of Water
1562 W. First Avenue
Columbus 12, Ohio

Nº 281165

County Summit Township Bath Section of Township _____

Owner Pyran Shoemaker Address 570 Graham Rd., Cuyahoga Falls, O.

Location of property 2544 Banning Road, Akron 13, Ohio

CONSTRUCTION DETAILS

Casing diameter 5" Length of casing 43'
Type of screen None Length of screen _____
Type of pump _____
Capacity of pump _____
Depth of pump setting _____
Date of completion 11/13/63

BAILING OR PUMPING TEST

~~Bailing~~
Pumping Rate 10 G.P.M. Duration of test 1 hrs.
Drawdown 4 ft. Date 11/13/63
Static level-depth to water 45 ft.
Quality (clear, cloudy, taste, odor) Clear
Pump installed by _____

WELL LOG

Formations Sandstone, shale, limestone, gravel and clay	From	To
Yellow Clay	0 Feet	19 Ft.
Blue Clay	19	36
Soft Shale	36	41
Shale Rock	41	80 T. D.

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.

N.

W.

E.

S.

See reverse side for instructions

Drilling Firm L. P. Cranz

Date 11/18/63

Address 2254 Ira Road, Akron 13, Ohio

Signed

L. P. Cranz