

WELL LOG AND DRILLING REPORT

ORIGINAL

PLEASE USE PENCIL
OR TYPEWRITER
DO NOT USE INK.

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1562 W. First Avenue
Columbus 12, Ohio

374
No 281168

County Medina Township Sharon Section of Township _____

Owner Arthur W. Dixon Address 1156 Medina Rd., R. D. #2, Medina, Ohio

Location of property 1156 Medina Rd.

CONSTRUCTION DETAILS

Casing diameter 5" Length of casing 47'
Type of screen None Length of screen _____
Type of pump None
Capacity of pump _____
Depth of pump setting _____
Date of completion 5/24/64

BAILING OR PUMPING TEST


Bailing _____
Pumping Rate 6 G.P.M. Duration of test 1 hrs.
Drawdown 4 ft. Date 5/24/64
Static level-depth to water 45 ft.
Quality (clear, cloudy, taste, odor) Clear
Pump installed by _____

WELL LOG

Formations Sandstone, shale, limestone, gravel and clay	From	To
Yellow Clay	0 Feet	17 Ft.
Blue Clay	17	45
Sand Stone	45	60 T. D.

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



Drilling Firm L. P. Cranz

Date 5/31/64

Address 2254 Ira Road, Akron 13, Ohio

Signed L. P. Cranz

LOCATED
94