

WELL LOG AND DRILLING REPORT

ORIGINAL

PLEASE USE PENCIL
OR TYPEWRITER
DO NOT USE INK.

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1562 W. First Avenue
Columbus 12, Ohio

No 282309

County LORAIN Township CARLISLE Section of Township _____
Owner L. H. GARTON Address RD #2, W. RIDGE RD., ELYRIA, O
Location of property 1/2 MI. N. INT. W. RIDGE. + BUTTERNUT RIDGE, RD.

CONSTRUCTION DETAILS	BAILING OR PUMPING TEST
Casing diameter <u>6" OD</u> Length of casing <u>7 FT.</u>	Pumping Rate <u>5</u> G.P.M. Duration of test <u>2 1/2</u> hrs.
Type of screen _____ Length of screen _____	Drawdown <u>BOTTOM</u> ft. Date <u>8/8/62</u>
Type of pump _____	Static level-depth to water <u>5</u> ft.
Capacity of pump _____	Quality (clear, cloudy, taste, odor) <u>CLEAR</u>
Depth of pump setting _____	Pump installed by _____
Date of completion <u>8/8/62</u>	

WELL LOG			SKETCH SHOWING LOCATION
Formations Sandstone, shale, limestone, gravel and clay	From	To	Locate in reference to numbered State Highways, St. Intersections, County roads, etc.
	0 Feet	_____ Ft.	
<u>yellow clay</u>	<u>0</u>	<u>7</u>	
<u>Berea Sandstone</u>	<u>7</u>	<u>18</u>	
<u>Gray Slate</u>	<u>18</u>	<u>23</u>	
<u>Red Slate</u>	<u>23</u>	<u>30</u>	
<u>Well makes;</u> <u>5 GPM 7-18 FT.</u>			See reverse side for instructions

Drilling Firm Harry M. Clelland & Son
Address 398 N. Olive St.
Elyria, O.

Date 8/29/62
Signed William C. M. Clelland