

WELL LOG AND DRILLING REPORT

ORIGINAL

PLEASE USE PENCIL
OR TYPEWRITER
DO NOT USE INK.

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1562 W. First Avenue
Columbus 12, Ohio

No 282310

County LORAIN Township LAGRANGE Section of Township _____

Owner WM. GREGORY Address BOX 396, LAGRANGE, O.

Location of property 1000 FT. N. INT. WHITEHEAD + ST. RTE 303

CONSTRUCTION DETAILS

Casing diameter 5 1/2" OD Length of casing 46 FT.
Type of screen _____ Length of screen _____
Type of pump _____
Capacity of pump _____
Depth of pump setting _____
Date of completion 8/11/62

BAILING OR PUMPING TEST

Pumping Rate 2 1/2 G.P.M. Duration of test 3 hrs.
Drawdown BOTTOM ft. Date 8/11/62
Static level-depth to water 11 ft.
Quality (clear, cloudy, taste, odor) CLEAR
Pump installed by _____


WELL LOG

Formations Sandstone, shale, limestone, gravel and clay	From	To
	0 Feet	_____ Ft.
yellow clay	0	11
Gray clay	11	14
Soft Gray Sandstone	14	46
Berea Sandstone	46	54
Gray Slate	54	59
Red shale	59	60

Well makes;
2 1/2 GPM 51-54 FT.

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



See reverse side for instructions

Drilling Firm Harry M. Chelland & Son Date 9/20/62

Address 398 N. Olive St. Signed William C. M. Chelland

Clyria, O.