WELL LOG AND DRILLING REPORT

ORIGINAL

PLEASE USE PENCIL OR TYPEWRITER DO NOT USE INK.

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1562 W. First Avenue
Columbus 12, Ohio

No 282415

County WOOD Township MONTGOMERY Section of Township 17

Owner MRS. FOSTER DUCK FARM Address WAYNE, OHIO

Location of property STATE Route 23 RUNS THRU DUCK FARM

CONSTRUCTION DETAILS

Casing diameter 5-3/8 Length of casing 25 Ft.

Type of screen NO SCREEN Length of screen O. STOE

Type of pump Submersible

Capacity of pump 650 Gal a HR.

Depth of pump setting 115 FT.

Date of completion April 26. 1965

BAILING OR PUMPING TEST

Pumping Rate 650 G.P.M. Duration of test 10 hrs.

Drawdown 80 ft. Date

Static level-depth to water 18 ft.

Quality (clear, cloudy, taste, odor) CLEAR

BY STATE TEST

Pump installed by Worlen. RISINGSUN

WELL LOG 125 Ft Steel

Formations Sandstone, shale, limestone, gravel and clay	From	To
Clay and gravel	0 Feet	.....Ft.
topped Rock at	16	
Hard Rock at	18	

SKETCH SHOWING LOCATION

Locate in reference to numbered State Highways, St. Intersections, County roads, etc.



See reverse side for instructions

Drilling Firm Melvin Good Date COMP. APRIL 26 - 1965

Address Fostoria O. 127 E FREMONT St. Signed Melvin Good.

83