

WELL LOG AND DRILLING REPORT

ORIGINAL

PLEASE USE PENCIL
OR TYPEWRITER
DO NOT USE INK.

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1562 W. First Avenue
Columbus 12, Ohio

No 286602

County Auglaize Township St Marys Section of Township _____
Owner Dewey Mallory Address St Marys O. R.R. 2
Location of property 2 miles south of St Marys O. on R.R. 66A

CONSTRUCTION DETAILS

Casing diameter 4 1/4" Length of casing 65 ft
Type of screen _____ Length of screen _____
Type of pump _____
Capacity of pump _____
Depth of pump setting _____
Date of completion _____

BAILING OR PUMPING TEST


Pumping Rate 18 G.P.M. Duration of test 1/2 hr.
Drawdown None ft. Date Nov. 2 - 1962
Static level-depth to water 20 ft.
Quality (clear, cloudy, taste, odor) Clear
Pump installed by _____

WELL LOG

Formations Sandstone, shale, limestone, gravel and clay	From	To
Blue clay	0 Feet	29 Ft.
Dark sand	29	37
Blue clay.	37	62
Sand & Gravel	62	63
Limestone	63 feet	
Depth	114 feet	

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



See reverse side for instructions

Drilling Firm Sheldon Lynch
Address R.R. #2 Napoleon

Date Nov. 2 - 62
Signed Sheldon Lynch

LOCATED

20