

WELL LOG AND DRILLING REPORT

ORIGINAL

PLEASE USE PENCIL
OR TYPEWRITER
DO NOT USE INK.

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1562 W. First Avenue
Columbus 12, Ohio

No 286743

County Auglaize Township St Marys Section of Township 18
Owner Mr Paul E. Funderdall Address 6209 Cruxton Dr Dayton
Location of property 2 mile West 364 and 1/2 mile north to St Marys
Ohio

CONSTRUCTION DETAILS		BAILING OR PUMPING TEST	
Casing diameter <u>4 1/4</u>	Length of casing <u>64 ft</u>	Pumping Rate <u>18</u> G.P.M.	Duration of test <u>2</u> hrs.
Type of screen	Length of screen	Drawdown <u>24</u> ft.	Date <u>Sept 3 1965</u>
Type of pump		Static level-depth to water <u>6 ft</u>	ft.
Capacity of pump		Quality (clear, cloudy, taste, odor) <u>Cloudy</u>	
Depth of pump setting <u>24 ft</u>			
Date of completion <u>Sept 3 1965</u>		Pump installed by	

WELL LOG			SKETCH SHOWING LOCATION	
Formations Sandstone, shale, limestone, gravel and clay	From	To	Locate in reference to numbered State Highways, St. Intersections, County roads, etc.	
<u>Top Soil</u>	<u>0 Feet</u>	<u>20 Ft.</u>		
<u>Blue Mud</u>	<u>20</u>	<u>60</u>		
<u>Sand & Gravel</u>	<u>60</u>	<u>64</u>		
<u>Lime Stone</u>	<u>64</u>	<u>106</u>		

See reverse side for instructions

Drilling Firm J. J. Truck
Address New Knoxville
Ohio

Date Sept 3 1965
Signed Paul E. Funderdall

LOCATED
37