

WELL LOG AND DRILLING REPORT

ORIGINAL

PLEASE USE PENCIL
OR TYPEWRITER
DO NOT USE INK.

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1562 W. First Avenue
Columbus 12, Ohio

No 286882

County Pickaway Township Salt Creek Section of Township 28
Owner 1 mile N.E. of Whisler, O Address Zubana, Ohio.
Location of property William Hoover

CONSTRUCTION DETAILS

Casing diameter 5 Length of casing 110
Type of screen Length of screen
Type of pump
Capacity of pump
Depth of pump setting
Date of completion Jan. 16, 1969

BAILING OR PUMPING TEST

Pumping Rate G.P.M. Duration of test hrs.
Drawdown ft. Date
Static level-depth to water ft.
Quality (clear, cloudy, taste, odor)
Pump installed by


WELL LOG

Formations Sandstone, shale, limestone, gravel and clay	From	To
	0 Feet	27 Ft.
Brown sandy mud	27	34
Blue mud	54	55
muddy sand	55	60
Soft shale	60	117
gray mud	117	152
Blue shale		
mixed with thin rock		
little muddy water		
at 54 ft.		
dry hole		
using steel cased		

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.

Note from driller: **N.**
Test hole for a proposed Nursing Home.



See reverse side for instructions

Drilling Firm Harold Lowery
Address Laurelville, O.

Date Apr. 6, 1969
Signed Harold Lowery