

WELL LOG AND DRILLING REPORT

ORIGINAL

PLEASE USE PENCIL
OR TYPEWRITER
DO NOT USE INK.

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1562 W. First Avenue
Columbus 12, Ohio

No 287162

County Madison Township Pleasant Section of Township.....
Owner Richard Lee Lewis Address Rt. 1, Mt Sterling, O.
Location of property S.W. Corner of Mt Sterling in Burr Oak Div.

CONSTRUCTION DETAILS	BAILING OR PUMPING TEST
Casing diameter <u>4 1/4"</u> Length of casing <u>83'</u>	Bailed Pumping Rate <u>1.0</u> G.P.M. Duration of test.....hrs.
Type of screen..... Length of screen.....	Drawdown <u>none</u> ft. Date.....
Type of pump.....	Static level-depth to water..... <u>50</u> ft.
Capacity of pump.....	Quality (clear, cloudy, taste, odor)..... <u>clear</u>
Depth of pump setting.....	Pump installed by.....
Date of completion <u>12-17-63</u>	

WELL LOG			SKETCH SHOWING LOCATION
Formations Sandstone, shale, limestone, gravel and clay	From	To	Locate in reference to numbered State Highways, St. Intersections, County roads, etc. N. S. E.
<u>Clay</u> <u>Blue clay</u> <u>Sand-gravel</u> <u>Blue clay</u> <u>gravel-water</u>	<u>0 Feet</u> <u>21</u> <u>33</u> <u>35</u> <u>83</u>	<u>21 Ft.</u> <u>33</u> <u>35</u> <u>83</u>	

Drilling Firm E. E. COMBS
Contractor
Address Route No. 1 Orient, Ohio

Date 12-17-63
Signed E. E. Combs

SECOND SET.

A4