

WELL LOG AND DRILLING REPORT

ORIGINAL

PLEASE USE PENCIL
OR TYPEWRITER
DO NOT USE INK.

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1562 W. First Avenue
Columbus 12, Ohio

No 287436

County Mahoning Township Ellsworth Section of Township One
Owner Lee Barnes Address R.2.D. #4 Salem
Location of property Duck Creek Road

CONSTRUCTION DETAILS

Casing diameter 6 5/8 in Length of casing 40 ft
Type of screen _____ Length of screen _____
Type of pump _____
Capacity of pump _____
Depth of pump setting _____
Date of completion _____

BAILING OR PUMPING TEST


Pumping Rate 24 G.P.M. Duration of test 2 hrs.
Drawdown 30 ft. Date August 8 1964
Static level-depth to water 14 ft.
Quality (clear, cloudy, taste, odor) Clear
18 hard 12 ss iron
Pump installed by _____

WELL LOG

Formations Sandstone, shale, limestone, gravel and clay	From	To
<u>Clay</u>	<u>0 Feet</u>	<u>10 Ft.</u>
<u>Gravel</u>	<u>10 ft.</u>	<u>18 ft.</u>
<u>Sand & Gravel</u>	<u>18 ft.</u>	<u>39 ft.</u>
<u>Shale Rock</u>	<u>39 ft.</u>	<u>45 ft.</u>
<u>Sand Rock</u>	<u>45 ft.</u>	<u>48 ft.</u>
<u>water at</u> <u>44 ft.</u> <u>20 S.P.M.</u>		

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



See reverse side for instructions

Drilling Firm L. D. Chingman Date August 10 1964
Address R.2.D. #4 Salem Ohio Signed John S. Chingman