

135

WELL LOG AND DRILLING REPORT

PLEASE USE PENCIL
OR TYPEWRITER
DO NOT USE INK.

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1562 W. First Avenue
Columbus 12, Ohio

No 289152

County Mahoning Township Smith Section of Township 10, 12, 21
Owner Samuel Wiley Address Minerva Ohio
Location of property Oak St, Smith 14

CONSTRUCTION DETAILS

Casing diameter 5 in Length of casing 38 1/2
Type of screen _____ Length of screen _____
Type of pump _____
Capacity of pump 6 G.P.M.
Depth of pump setting 105 ft
Date of completion Mar 28 - 67

BAILING OR PUMPING TEST

Pumping Rate 4 G.P.M. Duration of test 1 1/2 hrs.
Drawdown 100 ft. Date Mar 28 - 67
Static level-depth to water 15 ft ft.
Quality (clear, cloudy, taste, odor) clear
Pump installed by Carlyfather Drilling Co

WELL LOG

Formations Sandstone, shale, limestone, gravel and clay	From	To
	0 Feet	Ft.
clay	0	10
sand	10	21
muck	21	26
slate & coal	26	30
clay	30	36
slate	36	77
limestone	77	75
slate	75	90
limestone	90	92
slate	92	105
limestone	105	107
slate	107	115
limestone	115	117
slate	117	125

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.

N. will
Oak St
W. W. 12 Ave
S. 62 E.
Dangle Rd

S. Elev. of Rock: 1044

See reverse side for instructions

Drilling Firm Carlyfather Drilling Co Date Mar 28 - 67
Address Minerva O Signed H H Carlyfather

LOCATED

135