



WELL LOG AND DRILLING REPORT

36

NO. 28973

County Preble Township Harrison Section of Township 18.
Owner Raymond Thompson Address RR 2 Lewisburg, O
Location of property 2 mi W. of W. Sonora SR 503

CONSTRUCTION DETAILS

BAILING OR PUMPING TEST

Casing diameter 4" Length of casing 148' Pumping rate _____ G.P.M.
Type of screen _____ Length of screen _____ Duration of test _____ hrs.
Type of pump _____ Drawdown _____ ft. Date _____
Capacity of pump _____ Developed capacity _____
Depth of pump setting _____ Static level - depth to water 11 ft.
Date of completion _____ Pump installed by _____

WELL LOG

SKETCH SHOWING LOCATION

Formation

From

To

N.

red clay
br. clay
sand
br. clay
sand
ls.

0

12

32

41

124

145

160

W.

E.

water - 160'

S.

Drilling Firm Amzi Dull + SonDate 10-1-59

Address _____

Copied by RS

36