

WELL LOG AND DRILLING REPORT

ORIGINAL

18

PLEASE USE PENCIL
OR TYPEWRITER
DO NOT USE INK.

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1562 W. First Avenue
Columbus 12, Ohio

Nº 290606

County Logan Township Jefferson Section of Township 27

Owner Gerald Link Address Bellevue

Location of property 1 mi S of Bellevue on Ludlow Rd. to Fairground Rd
1st house on right

CONSTRUCTION DETAILS

Casing diameter 4 1/4 Length of casing 37
Type of screen _____ Length of screen _____
Type of pump _____
Capacity of pump _____
Depth of pump setting owner
Date of completion _____

BAILING OR PUMPING TEST

Pumping Rate 15 G.P.M. Duration of test _____ hrs.
Drawdown 0 ft. Date July 8-63
Static level-depth to water 410 ft.
Quality (clear, cloudy, taste, odor) Clear
Pump installed by owner

WELL LOG

Formations Sandstone, shale, limestone, gravel and clay	From	To
	0 Feet	Ft.
<u>Top Soil</u>		<u>2</u>
<u>Hard Pan</u>	<u>2</u>	<u>18</u>
<u>Dry Gravel</u>	<u>10</u>	<u>37</u>
<u>Brown Lime</u>	<u>37</u>	<u>81</u>
<u>Water at</u>	<u>81</u>	

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.

Bellevue N.
Ludlow Rd. E.
Fairground Rd. S.
See reverse side for instructions

Drilling Firm Don E. Harper
Address Bellevue R4

Date Jan 26 64
Signed Don E. Harper

