

WELL LOG AND DRILLING REPORT

ORIGINAL

44

PLEASE USE PENCIL
OR TYPEWRITER
DO NOT USE INK.

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1562 W. First Avenue
Columbus 12, Ohio.

Nº 290607

County Logan Township Winton Section of Township 26
Owner Hale Clemens Address Bellevue
Location of property 2 1/2 mi S on 68 to Clemens Allotment

CONSTRUCTION DETAILS	BAILING OR PUMPING TEST
Casing diameter <u>4 1/4</u> Length of casing <u>41</u>	Pumping Rate <u>15</u> G.P.M. Duration of test <u>2</u> hrs.
Type of screen..... Length of screen.....	Drawdown <u>0</u> ft. Date <u>July 27-67</u>
Type of pump.....	Static level-depth to water <u>15</u> ft.
Capacity of pump.....	Quality (clear, cloudy, taste, odor) <u>Clear</u>
Depth of pump setting <u>PUTTER</u>	Pump installed by <u>Owner</u>
Date of completion.....	

WELL LOG			SKETCH SHOWING LOCATION
Formations Sandstone, shale, limestone, gravel and clay	From 0 Feet	ToFt.	Locate in reference to numbered State Highways, St. Intersections, County roads, etc.
<u>Top Soil</u>		<u>4</u>	
<u>Gray Clay</u>	<u>4</u>	<u>39</u>	
<u>Fine Sand</u>	<u>39</u>	<u>40</u>	
<u>Gravel & Sand</u>	<u>40</u>	<u>41</u>	
<u>Water at</u>	<u>41</u>		

Drilling Firm Dan E. Karpert
Address Bellevue R 4

Date April 26-67
Signed Dan E. Karpert

