

WEI LOG AND DRILLING REPORT

ORIGINAL

PLEASE USE PENCIL
OR TYPEWRITER
DO NOT USE INK.

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1562 W. First Avenue
Columbus 12, Ohio

No 291149

County Allen Township American Section of Township 28
Owner S. J. Richman Address 23722 Sterling Place
Location of property 200' East of Stevick Rd on S.R. 81

CONSTRUCTION DETAILS

Casing diameter 4 1/4 Length of casing 41
Type of screen Length of screen
Type of pump Deep well jet
Capacity of pump 10 GPM
Depth of pump setting 60'
Date of completion 1-29

BAILING OR PUMPING TEST


Bake
Pumping Rate 10 G.P.M. Duration of test 1 hrs.
Drawdown 5 ft. Date 1-29-64
Static level-depth to water 45 ft.
Quality (clear, cloudy, taste, odor) Clear
Pump installed by R. Lehman

WELL LOG

Formations Sandstone, shale, limestone, gravel and clay	From	To
	0 Feet	Ft.
Clay	0	9
Sand	9	15
Clay	15	27
Clay + gravel	27	39
Sand	39	40
Limestone	40	113

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



See reverse side for instructions

Drilling Firm Robert F. Lehman
Address 2955 Shawnee Rd
Lima

Date 1-30-64
Signed Robert F. Lehman

