

WELL LOG AND DRILLING REPORT

ORIGINAL

PLEASE USE PENCIL
OR TYPEWRITER
DO NOT USE INK.

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1562 W. First Avenue
Columbus 12, Ohio

No 291434

County Portage Township Brinfield Section of Township
Owner Albert Baby Address 4756 Magadore Rd. Kent
Location of property Same - 4756 Magadore Rd. Kent

CONSTRUCTION DETAILS	BAILING OR PUMPING TEST
Casing diameter <u>4"</u> Length of casing <u>70'</u>	Pumping Rate <u>15</u> G.P.M. Duration of test <u>1 1/2</u> hrs.
Type of screen <u> </u> Length of screen <u> </u>	Drawdown <u>none</u> ft. Date <u> </u>
Type of pump <u> </u>	Static level-depth to water <u>4.5</u> ft.
Capacity of pump <u> </u>	Quality (clear, cloudy, taste, odor) <u> </u>
Depth of pump setting <u> </u>	<u> </u>
Date of completion <u> </u>	Pump installed by <u> </u>

WELL LOG			SKETCH SHOWING LOCATION
Formations Sandstone, shale, limestone, gravel and clay	From	To	Locate in reference to numbered State Highways, St. Intersections, County roads, etc. W. <u>Portage</u> <u>Magadore Rd.</u> <u>18</u> E.
	0 Feet	Ft.	
<u>clay</u>		<u>12</u>	
<u>sand & gravel</u>	<u>12</u>	<u>20</u>	
<u>Blue clay</u>	<u>20</u>	<u>25</u>	
<u>sand</u>	<u>25</u>	<u>55</u>	
<u>gravel</u>	<u>55</u>	<u>60</u>	
<u>sand</u>	<u>60</u>	<u>65</u>	
<u>gravel</u>	<u>65</u>	<u>70</u>	
<u>sand & stone</u>	<u>70</u>	<u>90'</u>	

S.
See reverse side for instructions

Drilling Firm Joseph Branecky Date 10/31-63
Address 152 State Rd. 18 Signed Joseph Branecky
Kent Ohio

