

WELL LOG AND DRILLING REPORT

ORIGINAL

PLEASE USE PENCIL
OR TYPEWRITER
DO NOT USE INK.

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1562 W. First Avenue
Columbus 12, Ohio

No 291435

County Portage Township Brimsfield Section of Township
Owner Frank Marker Address 1730 State Rd 18
Location of property Same - Kent Ohio

CONSTRUCTION DETAILS	BAILING OR PUMPING TEST
Casing diameter <u>4"</u> Length of casing <u>51'</u>	Pumping Rate <u>15</u> G.P.M. Duration of test <u>1</u> hrs.
Type of screen <u> </u> Length of screen <u> </u>	Drawdown <u>none</u> ft. Date <u> </u>
Type of pump <u> </u>	Static level-depth to water <u>30</u> ft.
Capacity of pump <u> </u>	Quality (clear, cloudy, taste, odor) <u> </u>
Depth of pump setting <u> </u>	
Date of completion <u> </u>	Pump installed by <u> </u>

WELL LOG			SKETCH SHOWING LOCATION
Formations Sandstone, shale, limestone, gravel and clay	From	To	Locate in reference to numbered State Highways, St. Intersections, County roads, etc.
	0 Feet	Ft.	
<u>Clay</u>		<u>10</u>	<u>Route 18</u> <u>43</u> <u>Route 18</u>
<u>Sandstone</u>	<u>10</u>	<u>26</u>	
<u>Shale</u>	<u>26</u>	<u>35</u>	
<u>Gravel</u>	<u>35</u>	<u>40</u>	
<u>Sand Gravel</u>	<u>40</u>	<u>45</u>	
<u>Red sandstone</u>	<u>45</u>	<u>51</u>	
<u>Red sandstone</u>	<u>51</u>	<u>55</u>	
<u>White sandstone</u>	<u>55</u>	<u>70</u>	

See reverse side for instructions

Drilling Firm Joseph Branch Date 11/8/63
Address 152 State Rd Signed Joseph Branch
18 - Kent Ohio

