

WELL LOG AND DRILLING REPORT

ORIGINAL

PLEASE USE PENCIL
OR TYPEWRITER
DO NOT USE INK.

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1562 W. First Avenue
Columbus 12, Ohio

4
Nº 291438

County Portage Township Brimfield Section of Township _____
Owner Marcel Alayoff Address 4607 Edson Rd Kent Ohio
Location of property same — 4607-Edson Rd Kent Ohio

CONSTRUCTION DETAILS

Casing diameter 4" Length of casing 94'
Type of screen _____ Length of screen _____
Type of pump _____
Capacity of pump _____
Depth of pump setting _____
Date of completion _____

BAILING OR PUMPING TEST


Pumping Rate 1.8 G.P.M. Duration of test 1 1/2 hrs.
Drawdown 0 ft. Date _____
Static level-depth to water 60 ft.
Quality (clear, cloudy, taste, odor) _____
Pump installed by _____

WELL LOG

Formations Sandstone, shale, limestone, gravel and clay	From	To
	0 Feet	_____ Ft.
<u>Clay</u>		<u>10</u>
<u>Sand & Gravel</u>	<u>12</u>	<u>25</u>
<u>Sand</u>	<u>25</u>	<u>30</u>
<u>Blue Clay</u>	<u>30</u>	<u>35</u>
<u>Sand</u>	<u>35</u>	<u>60</u>
<u>Gravel</u>	<u>60</u>	<u>65</u>
<u>Sand & Gravel</u>	<u>65</u>	<u>94</u>
<u>Sandstone</u>	<u>94</u>	<u>120'</u>

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



See reverse side for instructions

Drilling Firm Joseph Bransky
Address 152 State St. 1st
Kent, Ohio

Date 1-25-64
Signed Joseph Bransky
LOCKED