

WELL LOG AND DRILLING REPORT

ORIGINAL

PLEASE USE PENCIL
OR TYPEWRITER
DO NOT USE INK.

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1562 W. First Avenue
Columbus 12, Ohio

No 295913

County Guernsey Township Center Section of Township 2
Owner James Ross Address Lore City RD 1 Ohio
Location of property On Co. Road 60 - 1 mi. N. Kipling, Ohio

CONSTRUCTION DETAILS		BAILING OR PUMPING TEST	
Casing diameter <u>5 1/2"</u>	Length of casing <u>76' ft</u>	Pumping Rate <u>5</u> G.P.M.	Duration of test <u>1 hr only</u>
Type of screen <u>-</u>	Length of screen <u>-</u>	Drawdown <u>Bail Test</u> ft.	Date <u>7/14/63</u>
Type of pump <u>-</u>		Static level-depth to water <u>18'</u> ft.	
Capacity of pump <u>Jet Deepwell</u>		Quality (clear, cloudy, taste, odor) <u>good Taste</u>	
Depth of pump setting <u>By owner</u>		<u>Not settled yet</u>	
Date of completion <u>7/16/63</u>		Pump installed by <u>Owner</u>	

WELL LOG			SKETCH SHOWING LOCATION
Formations Sandstone, shale, limestone, gravel and clay	From	To	Locate in reference to numbered State Highways, St. Intersections, County roads, etc.
<u>Clay + Ssill</u>	<u>0 Feet</u>	<u>3</u> Ft.	N. Center Twp (2^{Sec.}) US 40 OH 49 St W. E. Ross well X 1 mi Kipling, O. S. See reverse side for instructions
<u>Br. Sandrock</u>	<u>3</u>	<u>10</u>	
<u>Blue Core</u>	<u>10</u>	<u>18'</u>	
<u>Red Rock</u>	<u>18</u>	<u>55</u>	
<u>Limestone</u>	<u>55</u>	<u>60</u>	
<u>Red Shale</u>	<u>60</u>	<u>78</u>	
Water at <u>40' + 65'</u>			

Drilling Firm Marlatt & Sons Date 7/14/63
Address RT 3 Cambridge Ohio Signed James Ross