

WELL LOG AND DRILLING REPORT

ORIGINAL

PLEASE USE PENCIL
OR TYPEWRITER
DO NOT USE INK.

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1562 W. First Avenue
Columbus 12, Ohio

No 298573

County ALLEN Township AMANDA Section of Township 2
Owner LARRY L. MOWERY Address 411-EWING LIMA, OH
Location of property SUNDERLAND RD.

CONSTRUCTION DETAILS	BAILING OR PUMPING TEST
Casing diameter <u>4 1/4"</u> Length of casing <u>34'</u>	Pumping Rate <u>10</u> G.P.M. Duration of test <u>1</u> hrs.
Type of screen _____ Length of screen _____	Drawdown <u>NONE</u> ft. Date <u>May 15, 1964</u>
Type of pump _____	Static level-depth to water <u>22 ft.</u> ft.
Capacity of pump _____	Quality (clear, cloudy, taste, odor) <u>Clear</u>
Depth of pump setting _____	Pump installed by _____
Date of completion _____	

WELL LOG			SKETCH SHOWING LOCATION
Formations Sandstone, shale, limestone, gravel and clay	From	To	Locate in reference to numbered State Highways, St. Intersections, County roads, etc.
<u>CLAY</u> <u>LIMESTONE</u>	<u>0 Feet</u> <u>34</u>	<u>34 Ft.</u> <u>81</u>	

See reverse side for instructions

