

WE' LOG AND DRILLING REP (T

ORIGINAL

PLEASE USE PENCIL
OR TYPEWRITER
DO NOT USE INK.

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1562 W. First Avenue
Columbus 12, Ohio

No 298574

County ALLEN Township SHAWNEE Section of Township 3
Owner JAMES DAVIS Address 206 E 3rd St Lima, O.
Location of property SPRING VIEW DRIVE - WEST OF LIMA

CONSTRUCTION DETAILS

Casing diameter 4 1/4" Length of casing 122'
Type of screen..... Length of screen.....
Type of pump.....
Capacity of pump.....
Depth of pump setting.....
Date of completion.....

BAILING OR PUMPING TEST

Pumping Rate 10 G.P.M. Duration of test 1 hrs.
Drawdown 610 ft. Date 5-29-1964
Static level-depth to water 61 ft.
Quality (clear, cloudy, taste, odor) CLEAR
Pump installed by.....

WELL LOG

SKETCH SHOWING LOCATION

Formations
Sandstone, shale, limestone,
gravel and clay

From


To

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.

CLAY	0 Feet	40 Ft.
CEMENTED GRAVEL	40	50
CLAY	50	80
QUICK SAND	80	110
RED CLAY	110	115
SAND	115	122
GRAVEL	122	

W.

E.



S.

See reverse side for instructions

Drilling Firm W & R MEDAUGH

Date 5-29-1964

Address 2020 E. LIVINGSTON ST.

Signed Wm R. Medaugh

CELINA, OHIO