

WELL LOG AND DRILLING REPORT

ORIGINAL

PLEASE USE PENCIL
OR TYPEWRITER
DO NOT USE INK.

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1562 W. First Avenue
Columbus 12, Ohio

No 299674

County Stark Township Nimishillen Section of Township _____

Owner John Bentley Address 6101 Holly Dr. N.E. North
Canton 20

Location of property 6361 Peach St. N.E.

CONSTRUCTION DETAILS	BAILING OR PUMPING TEST
Casing diameter <u>4"</u> Length of casing <u>34'</u>	Pumping Rate <u>10</u> G.P.M. Duration of test <u>1</u> hrs.
Type of screen <u>None</u> Length of screen _____	Drawdown <u>32</u> ft. Date <u>9/16/63</u>
Type of pump _____	Static level-depth to water <u>78</u> ft.
Capacity of pump _____	Quality (clear, cloudy, taste, odor) <u>Clear</u>
Depth of pump setting _____	_____
Date of completion _____	Pump installed by _____

WELL LOG			SKETCH SHOWING LOCATION
Formations Sandstone, shale, limestone, gravel and clay	From	To	Locate in reference to numbered State Highways, St. Intersections, County roads, etc. N. W. E. S.
	0 Feet	_____ Ft.	
Clay		22	
Shale	22	32	
Limestone	32	35	
Shale	35	52	
Limestone	52	56	
Shale	56	100	
Sandstone	100	138	
Shale	138	153	
Sandstone	153	163	

See reverse side for instructions

Drilling Firm R. F. Murphy

Date Sept. 16, 1963

Address 6334 Manchester Rd.
RD #3 Clinton, Ohio.

Signed _____