

WELL LOG AND DRILLING REPORT

ORIGINAL

PLEASE USE PENCIL
OR TYPEWRITER
DO NOT USE INK.

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1562 W. First Avenue
Columbus 12, Ohio

No 301153

County Pickaway Township Jackson Section of Township N. W.
Owner Gary Owen Address Rt. #4 Circleville, Ohio
Location of property 7 miles on London-Northern Pike - Well on North Side of Road.

CONSTRUCTION DETAILS			BAILING OR PUMPING TEST	
Casing diameter <u>4"</u>	Length of casing.....		Pumping Rate <u>10</u> G.P.M.	Duration of test <u>4</u> hrs.
Type of screen.....	Length of screen.....		Drawdown <u>12</u> ft.	Date <u>Sept. 26, 1963</u>
Type of pump.....			Static level-depth to water <u>59</u> ft.	
Capacity of pump.....			Quality (clear, cloudy, taste, odor).....	
Depth of pump setting.....			Pump installed by.....	
Date of completion.....				
WELL LOG			SKETCH SHOWING LOCATION	
Formations Sandstone, shale, limestone, gravel and clay	From	To	Locate in reference to numbered State Highways, St. Intersections, County roads, etc.	
<u>clay</u>	0 Feet	<u>8</u> Ft.	N. S.	
<u>shale</u>	8	50		
<u>fine sand</u>	50	56		
<u>shale</u>	56	68		
<u>fine sand</u>	68	106		
<u>blue muck</u>	106	110		
<u>Coarse sand</u>	110	113		
<u>Coarse gravel</u>	113	116		

Drilling Firm Harley No 991 E
Address Circleville, Ohio

Date Dec. 30, 1963
Signed