

WELL LOG AND DRILLING REPORT

ORIGINAL

PLEASE USE PENCIL
OR TYPEWRITER
DO NOT USE INK.

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1562 W. First Avenue
Columbus 12, Ohio

No 301155

County Pickaway Township Walnut Section of Township N. E.
Owner Glenn Ett Address Rt # 2 Ashville, Ohio
Location of property one mile East of Walnut Twp. school - Well on North Side of Road.

CONSTRUCTION DETAILS

Casing diameter 4" Length of casing
Type of screen Length of screen
Type of pump
Capacity of pump
Depth of pump setting
Date of completion

BAILING OR PUMPING TEST


Pumping Rate 4 G.P.M. Duration of test 2 hrs.
Drawdown 4 ft. Date Oct. 14, 1963
Static level-depth to water 16 ft.
Quality (clear, cloudy, taste, odor)
Pump installed by

WELL LOG

Formations Sandstone, shale, limestone, gravel and clay	From	To
clay	0 Feet	4 Ft.
dry sand	4	10
blue clay	10	18
fine sand	18	20
coarse gravel	20	23

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



S.

See reverse side for instructions

Drilling Firm Harley Nozgle Date Dec. 30, 1963
Address 546 E. Main St. Ashville, Ohio Signed