

WELL LOG AND DRILLING REPORT

ORIGINAL

PLEASE USE PENCIL
OR TYPEWRITER
DO NOT USE INK.

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1562 W. First Avenue
Columbus 12, Ohio

No 301157

County Pickaway Township Walnut Section of Township N.E.
Owner Hinton Waites Address Rt # 2 Ashville
Location of property one mile North of Walnut Twp. School Well on East side of Road.

CONSTRUCTION DETAILS

Casing diameter 4" Length of casing.....
Type of screen..... Length of screen.....
Type of pump.....
Capacity of pump.....
Depth of pump setting.....
Date of completion.....

BAILING OR PUMPING TEST


Pumping Rate 8 G.P.M. Duration of test 2 hrs.
Drawdown 5 ft. Date Oct. 7, 1963
Static level-depth to water 16 ft.
Quality (clear, cloudy, taste, odor).....
Pump installed by.....

WELL LOG

Formations Sandstone, shale, limestone, gravel and clay	From	To
<u>Clay</u>	<u>0 Feet</u>	<u>7 Ft.</u>
<u>Shale</u>	<u>7</u>	<u>22</u>
<u>Sand</u>	<u>22</u>	<u>25</u>
<u>Coarse gravel</u>	<u>25</u>	<u>27</u>

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



S.

See reverse side for instructions

Drilling Firm Harley Noggle
Address Circleville, Ohio

Date Dec. 30, 1963

Signed

102