

WELL LOG AND DRILLING REPORT

ORIGINAL

PLEASE USE PENCIL
OR TYPEWRITER
DO NOT USE INK.

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1562 W. First Avenue
Columbus 12, Ohio

No 301344

County Stark Township Jackson Section of Township 21

Owner Shady Hollow Country Club Address 4865 Wales NW Massillon,

Location of property Same Ohio

CONSTRUCTION DETAILS

Casing diameter 10 Length of casing 33
Type of screen Prof. Length of screen 12 + 22
Type of pump
Capacity of pump
Depth of pump setting
Date of completion

BAILING OR PUMPING TEST

Pumping Rate 1500 G.P.M. Duration of test 5 hrs.
Drawdown 10 ft. Date
Static level-depth to water 0 ft.
Quality (clear, cloudy, taste, odor)
Pump installed by

WELL LOG

SKETCH SHOWING LOCATION

Formations
Sandstone, shale, limestone,
gravel and clay

From

To

0 Feet

Ft.

Gravel clay
Sand + Gravel
clay + mud
Sand + Gravel

21

45

45

63

63

85

W.

N.

E.

S.

See reverse side for instructions

Drilling Firm Geo. E. Martin + Son Date 7 Dec. 1964

Address 3103 Martindale Rd Signed Geo. E. Martin

Canton, Ohio

LOCATED
39