

WELL LOG AND DRILLING REPORT

ORIGINAL

PLEASE USE PENCIL
OR TYPEWRITER
DO NOT USE INK.

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1562 W. First Avenue
Columbus 12, Ohio


No 301347

County Stark Township Plain Section of Township 30

Owner J. W. Weaver Address 3650 Parkhill Circle

Location of property Same Canton, Ohio

CONSTRUCTION DETAILS	BAILING OR PUMPING TEST
Casing diameter <u>7 + 5</u> Length of casing <u>38 - 78</u>	<u>Bailing</u> Pumping Rate <u>18</u> G.P.M. Duration of test _____ hrs.
Type of screen _____ Length of screen _____	Drawdown <u>36</u> ft. Date _____
Type of pump <u>Sub.</u>	Static level-depth to water <u>41</u> ft.
Capacity of pump _____	Quality (clear, cloudy, taste, odor) _____
Depth of pump setting <u>84</u>	Pump installed by <u>Martin & Son</u>
Date of completion _____	

WELL LOG			SKETCH SHOWING LOCATION
Formations Sandstone, shale, limestone, gravel and clay	From	To	Locate in reference to numbered State Highways, St. Intersections, County roads, etc.
<u>Clay</u>	<u>0 Feet</u>	<u>12 Ft.</u>	N.  E. S. See reverse side for instructions
<u>Gravel + Stones</u>	<u>12</u>	<u>25</u>	
<u>Shale</u>	<u>25</u>	<u>37</u>	
<u>Limestone</u>	<u>37</u>	<u>40</u>	
<u>Soft Shale</u>	<u>40</u>	<u>63</u>	
<u>L. Gray shale</u>	<u>63</u>	<u>73</u>	
<u>Sandrock</u>	<u>73</u>	<u>90</u>	
<u>Light shale (sandy)</u>	<u>90</u>	<u>100</u>	

Drilling Firm Geo. E. Martin & Son

Date 5 Feb 1965

Address 3103 Martindale Rd

Signed E. E. Martin

Canton, O