

WELL LOG AND DRILLING REPORT

ORIGINAL

PLEASE USE PENCIL
OR TYPEWRITER
DO NOT USE INK.

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1562 W. First Avenue
Columbus 12, Ohio

No 301348

County Stark Township Lake Section of Township 14

Owner Clarence E Sloat Address 222 Jefferson S.E.

Location of property Same Hartsville, O

CONSTRUCTION DETAILS

Casing diameter 4 Length of casing 66
Type of screen _____ Length of screen _____
Type of pump Jet
Capacity of pump 10
Depth of pump setting 30
Date of completion _____

BAILING OR PUMPING TEST


Bailing 30 G.P.M. Duration of test _____ hrs.
Pumping Rate _____
Drawdown 5 ft. Date _____
Static level-depth to water 15 ft.
Quality (clear, cloudy, taste, odor) _____
Pump installed by Martin & Son

WELL LOG

Formations Sandstone, shale, limestone, gravel and clay	From	To
	0 Feet	_____ Ft.
<u>Clay & Stones</u>		<u>22</u>
<u>Sand</u>	<u>22</u>	<u>30</u>
<u>Clay Gravel</u>	<u>30</u>	<u>62</u>
<u>Sand & Gravel</u>	<u>62</u>	<u>66</u>

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



See reverse side for instructions

Drilling Firm Geo. E. Martin & Son Date 4 May 1965

Address 3103 Martindale Rd Signed _____
Canton, O