

WELL LOG AND DRILLING REPORT

ORIGINAL

PLEASE USE PENCIL
OR TYPEWRITER
DO NOT USE INK.

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1562 W. First Avenue
Columbus 12, Ohio

See ad ⑨
No 301763

County Washington Township Waterford Section of Township _____
Owner Orville Ball Address Waterford R.F.D. 2
Location of property (Lot) on County Road No 6

CONSTRUCTION DETAILS

Casing diameter 6.00 Length of casing 83
Type of screen _____ Length of screen _____
Type of pump _____
Capacity of pump _____
Depth of pump setting _____
Date of completion July 27-1966

BAILING OR PUMPING TEST

Pumping Rate _____ G.P.M. Duration of test _____ hrs.
Drawdown total ft. Date July 27
Static level-depth to water 28 ft ft.
Quality (clear, cloudy, taste, odor) Clear
Pump installed by Owner

WELL LOG

Formations Sandstone, shale, limestone, gravel and clay	From	To
Soil	0 Feet	10 Ft.
Drift or quick sand	10	20
Soft slate	20	25
Sand Shell	25	27
Lime slate	27	45
Slate	45	83


SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.

N.

W.

E.



See reverse side for instructions

Drilling Firm Leland Bunt
Address Stockport O

Date July 28-1966
Signed Leland Bunt

76