

WELL LOG AND DRILLING REPORT

ORIGINAL

State of Ohio

PLEASE USE PENCIL
OR TYPEWRITER
DO NOT USE INK.

DEPARTMENT OF NATURAL RESOURCES

Division of Water
1562 W. First Avenue
Columbus 12, Ohio

No 302338

County Captage Township Deerfield Section of Township Nearby
Owner Walter W. Henderson Address 9374 Yale Rd., Danford, O
Location of property 1/4 mile west of Rt 627 on Yale Rd. & south side

CONSTRUCTION DETAILS

Casing diameter 6 1/4 Length of casing 4-50
Type of screen — Length of screen —
Type of pump —
Capacity of pump —
Depth of pump setting 40'
Date of completion —

BAILING OR PUMPING TEST


Pumping Rate 15 G.P.M. Duration of test 2 hrs.
Drawdown 50 ft. Date July 23-64
Static level-depth to water 35 ft.
Quality (clear, cloudy, taste, odor) —
Pump installed by —

WELL LOG

Formations Sandstone, shale, limestone, gravel and clay	From	To
CLAY	0 Feet	30 Ft.
SHALE	50	80
GRAY STONE	80	97
SHALE	97	185
CONJUN SAND WATER	185	212

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



See reverse side for instructions

Drilling Firm Buckeye Drilling
Address 693 Bandy Rd.
Deerfield, O

Date 7-23-64
Signed Cathy Scott

