

WELL LOG AND DRILLING REPORT

ORIGINAL

PLEASE USE PENCIL
OR TYPEWRITER
DO NOT USE INK.

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1562 W. First Avenue
Columbus 12, Ohio

No 302842

County Summit Township Northampton Section of Township _____
Owner Ned Oliver Address 1068 1/2 Murray Ave. Guyahoga Falls, O.
Location of property Sub Lot # 74 Steels Corners Rd. Akron, Ohio

CONSTRUCTION DETAILS			BAILING OR PUMPING TEST	
Casing diameter <u>5 in.</u>	Length of casing <u>150 ft.</u>		Pumping Rate <u>20</u> G.P.M.	Duration of test <u>2</u> hrs.
Type of screen _____	Length of screen _____		Drawdown <u>none</u> ft.	Date <u>Oct. 25, 1963</u>
Type of pump _____			Static level-depth to water <u>75</u> ft.	
Capacity of pump _____			Quality (clear, cloudy, taste, odor) <u>clear</u>	
Depth of pump setting _____				
Date of completion <u>Oct. 25, 1963</u>			Pump installed by _____	
WELL LOG			SKETCH SHOWING LOCATION	
Formations Sandstone, shale, limestone, gravel and clay	From	To	Locate in reference to numbered State Highways, St. Intersections, County roads, etc.	
mud & sand	0 Feet	50 Ft.		
gray mud	50	100		
fine sand	100	137		
sand & gravel	137	147		
			S. See reverse side for instructions	

Drilling Firm Rhoades Drilling Co., Inc. Date Oct. 26, 1963
Address Box 474 Canal Fulton, Ohio Signed _____

148